Proposed Traffic Improvements

11.17.2014

Introduction

This document is intended to highlight the traffic improvements envisioned by the Austin Oaks Planned Unit Development (PUD). It addresses two sets of proposed improvements:

- 1. Those envisioned by a Traffic Impact Analysis (TIA) ongoing for the site; and
- 2. Additional traffic improvements that could be implemented by the project developer to further alleviate traffic and safety issues near the site, but not specifically related to the PUD.

Status of the Traffic Impact Analysis (TIA) Report

On June 26, 2014, Bury developed and submitted a Traffic Impact Analysis (TIA) Report related to the Austin Oaks Planned Unit Development (PUD). Based on comments received from the City, various stakeholders, and components of the project that have continued to evolve, a revision was submitted to the City of Austin on August 19, 2014. Review comments on this latest submittal are still pending from the City of Austin.


Description of Exhibits

The following sections of the document are organized according to the two sets of proposed improvements described above. Each sheet in this document presents a specific intersection near the Austin Oaks PUD, diagrams depicting the improvements related to the intersection, a list of the phased improvements planned for the intersection, and a graph showing expected Level of Service impacts against existing conditions.

Austin Oaks Planned Unit Development Proposed Traffic Improvements

Traffic Impact Analysis (TIA)

Intersections Studied as part of the TIA



The following intersections were studied as part of the Bury TIA:

- 1. Far West Boulevard & Hart Lane
- 2. Far West Boulevard & Wood Hollow Drive
- Far West Boulevard & Mopac Southbound Frontage Road
- 4. Far West Boulevard & Mopac Northbound Frontage Road
- Spicewood Springs Road & Mopac Southbound Frontage Road
- 6. Spicewood Springs Road & Mopac Northbound Frontage Road

- Spicewood Springs Road & Wood Hollow Drive/Private Driveway
- 8. Steck Avenue & Mopac Southbound Frontage Road
- Steck Avenue & Mopac Northbound Frontage Road
- 10. Greystone Drive & Hart Lane
- 11. Greystone Drive & Wood Hollow Drive
- 12. Executive Center Drive & Wood Hollow Drive
- 13. Executive Center Drive & Hart Lane
- 14. Spicewood Springs Road & Hart Lane

Far West Boulevard & Hart Lane



Improvement	Year	Estimated Cost (\$)
Restripe southbound Hart Lane approach to provide	2023	
southbound left turn lane and one shared thru right		
lane		
Signal modification for northbound and southbound	2023	
Hart Lane approaches		
Revise signal split timing	2023	



- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Far West Boulevard & Wood Hollow Drive




Intersection	Improvement	Year	Estimated Cost (\$)
Far West Boulevard &	Signal Modifications for	2028	
Wood Hollow Drive	northbound and southbound		
	Wood Hollow Drive approaches		
	Revise signal split timing	2028	




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Far West Boulevard & Mopac Southbound Frontage




Intersection	Improvement	Year	Estimated Cost (\$)
Far West Boulevard &	Revise signal split timing	2018	
Mopac Southbound			
Frontage			




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Far West Boulevard & Mopac Northbound Frontage




Intersection	Improvement	Year	Estimated Cost (\$)
Far West Boulevard &	Revise signal split timing	2018	
Mopac Northbound			
Frontage			




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Spicewood Springs Road & Mopac Southbound Frontage



Intersection	Improvement	Year	Estimated Cost (\$)
Spicewood Springs	Revise signal split timing	2018	
Road & Mopac			
Southbound Frontage			




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Spicewood Springs Road & Mopac Northbound Frontage



Intersection	Improvement	Year	Estimated Cost (\$)
Spicewood Springs	Revise signal split timing	2018	
Road & Mopac			
Northbound Frontage			



- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Spicewood Springs Road & Wood Hollow Drive/Private Drive




Intersection	Improvement	Year	Estimated Cost (\$)
Spicewood Springs	Restripe northbound Wood	2018	
Road and Wood	Hollow Drive to provide 3 lanes: 1		
Hollow Drive	northbound left turn lane, 1		
	shared thru right lane, and 1		
	northbound right turn lane		
	Revise signal split timing	2018	




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Steck Avenue & Mopac Southbound Frontage




Intersection	Improvement	Year	Estimated Cost (\$)
Steck Avenue &	Revise signal split timing	2018	
Mopac Southbound			
Frontage			




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Steck Avenue & Mopac Northbound Frontage




Intersection	Improvement	Year	Estimated Cost (\$)
Steck Avenue &	Revise signal split timing	2018	
Mopac Northbound			
Frontage			




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Greystone Drive & Hart Lane



Intersection	Improvement	Year	Estimated Cost (\$)
Greystone Drive & Hart	Stripe northbound and	2023	
Lane	southbound Hart Lane to provide 2 lanes: 1 shared left thru lane, & 1 shared thru right turn lane.		
	Restripe eastbound & westbound Greystone Drive approaches to provide shared left thru & shared thru right turn lanes.		s of Service:




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Greystone Drive & Wood Hollow Drive



Intersection	Improvement	Year	Estimated Cost (\$)
Greystone Drive &	Restripe eastbound and	2028	
Wood Hollow Drive	westbound Greystone Drive approaches to provide 1 shared left-thru and 1 shared thru right turn lane.		



- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Executive Center Drive & Wood Hollow Drive



Intersection	Improvement	Year	Estimated Cost (\$)
Executive Center Drive	Add a traffic signal.	2018	
& Wood Hollow Drive			




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Executive Center Drive & Hart Lane



Intersection	Improvement	Year	Estimated Cost (\$)
Executive Center Drive	Stripe northbound Executive	2028	
& Hart Lane	Center Drive approach to provide 2 lanes: 1 northbound left		
	turn lane and northbound right turn lane.		




- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Spicewood Springs Road & Hart Lane



Intersection	Improvement	Year	Estimated Cost (\$)
Spicewood Springs	Add a traffic signal.	2018	
Road & Hart Lane			



- A: Good progression and short cycle lengths.
- B: Good progression or short cycle lengths; more vehicle stops.
- C: Fair progression and/or longer cycle lengths; some cycle failures.
- D: Congestion becomes noticeable, high volume to capacity ratio.
- E: Limit of acceptable delay, poor progression, long cycles, and/or high volume
- F: Unacceptable to drivers; volume greater than capacity.

Austin Oaks Planned Unit Development Proposed Traffic Improvements

Potential Additional Improvements

Potential Additional Improvements

Location	Improvement	Year	Estimated Cost (\$)
Far West Boulevard &	Add a traffic signal.		\$420,000
Mesa			
Hart Lane	Construct sidewalks		\$10,000
Hart Lane	Construct speed cushions		\$40,000